
EN ISO 20471 Hi-Visibility Executive Warning Vest

Description: High Visibility Executive Warning Vest.

Code: WCENGEXEC SY/OR

Style Identification: Two bands around torso and one band over each shoulder.



2

EN ISO 20471 2013: Class 2 Area of Saturn Yellow or High Visibility Orange Background and Retro Reflective Tape

CE These garments bear CE marking to demonstrate compliance with EC Directive EC/686/89 Personal Protective Equipment Annex II Health & Safety

Limitations of Use: This garment is a conspicuity aid - Always wear the garment fastened at all times.

Keep Clean: To ensure optimum conspicuity this garment must be kept clean and regulare comparisons are recommended against a new garment.

Disposal: Please dispose of the garment in a responsible, safe manner.

Aftercare: For instructions on washing, see care label in garment. Company will not accept liability for garments where care labels have been ignored, neglected, defaced or removed.



Max. x 25 Wash Cycles

Do not wash in biological powder. Wash as synthetics. Machine Warm minimum wash. Warm Hand Wash. Cold rinse, short spin, do not wring.

The stated maximum number of cleaning cycles is not the only factor related to the lifetime of the garment.

The lifetime will also depend on usage, care, storage etc.


Storage & Transportation: Always store in clean, dry conditions. Do NOT store in places subject to direct, strong sunlight. This garment is suitable for transportation as supplied by the manufacturer.

Available Sizes and Selection

A larger size may be required if worn over other clothing.

Fit according to chest size:

Size:	Chest Size:	Height:
Medium	94 - 102	172 - 180
Large	102 - 110	180 - 188
XLarge	110 - 118	188 - 196
XXL	118 - 129	196 - 204
XXXL	129 - 141	196 - 204



SEEN

P.O. Box 13636, West Bromwich, B70 1BQ

Notified Body: ITS Testing Services (UK) Ltd, Meridian Business Park, Leicester, LE19 1WD. NB No. (0362)

Polyester with Reflective Tape

EN ISO 20471 2013

High Visibility Warning
Clothing

CE



WCENGEXEC SY/OR

This garment must be kept clean to be effective.
Replace if permanently stained or faded.



Rinse well drip dry.
Max 25

P.O. Box 13636,
West Bromwich, B70 1BQ